

# C201 Software Release Notes



## C201 Software Pack - Revision AE

7022069\_AE\_\_C201.zip

C201 Software Pack AE	
Release Date:	08. August 2018
Engineer:	Markus Auer (Bucher Municipal AG)

Hardware & Software Summary		
Device	Previous Version (AD)	New Version (AE)
Software PLC:	2.30	<b>2.40</b>
Software HMI:	2.20	2.20
JetSym	5.4.1.4256	5.4.1.4256
JetViewSoft	5.3.0.4030	5.3.0.4030
JVM BL	1.11.0.00	1.11.0.00
JVM 407 OS	1.23.1.00	1.23.1.00
JVM 407B OS	4.01.0.63	4.01.0.63
Tx5 OS	0.07.3.23	0.07.3.23
IO Node OS	3.32.0.01	3.32.0.01
PRN OS	1.04.0.00	1.04.0.00

**BUCHER**  
municipal

Confidential. All Rights Reserved  
Distribution or Copies Prohibited  
© 2018 Copyright Johnston Sweepers Limited

# C201 Software Release Notes

## Warning

**\*\* Following JVM update, do not start engine until an “Ignition ready” key on – key off cycle is completed.\*\***

## Note

**The Euro 5 machines are not supported anymore with revision AD or higher.**

## JVM PLC

**Update:** Version: 2.40

**Bug Fixes:**

1. sidebrush speed to slow (65 RPM instead of 130 RPM)

## JVM HMI

No changes

## Tx5 PLC

No changes

**BUCHER**  
municipal

Confidential. All Rights Reserved  
Distribution or Copies Prohibited  
© 2018 Copyright Johnston Sweepers Limited